25X1

Ceggr 5 of 5

10 July 1956

HENCEANUM FOR: Director of Material

SUBJECT:

Soundpreading of Doors in Room 536

Apparently, through oversight, several doors in the 536 complex were not soundproaded properly when the eriginal modification of these rooms took place. Request you take action as soon as possible to relieve these deficiencies.

25X1

Director of Material

MCMylm

1 & 2 - Addresses

3 - Ope maj

4 - Ope chron

5 - Admin chron

0801000

<sub>0.0</sub>05009